ASH GROVE CEMENT COMPANY

"WESTERN REGION"

July 13, 1995

Ms. Melissa McAfee
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500
Seattle, WA. 98101-2038

Re: Notice of Violation #33756 and 33757

Dear Ms. McAfee,

The Notice of Violation #33756 and #33757 issued July 3, 1995 requires a report from Ash Grove on proposed actions to be taken to achieve continuous compliance.

NOV #33756

This event which occurred on June 29, 1995 is a condition of process start up which has been addressed by a Best Available Control Technology (BACT) Determination submitted to PSAPCA on April 27, 1995.

NOV #33757

This NOV adds sections 9.15(a) and 9.15(c) to NOV #33290 issued for a June 22, 1995 event. A response was provided to PSAPCA on June 28, 1995 and explained this event as a condition of process start up which has been addressed by a Best Available Control Technology (BACT) Determination submitted to PSAPCA on April 27, 1995.

Ash Grove awaits a response from PSAPCA on the BACT study.

Sincerely, yours,

Gerald J. Brown

Manager, Safety and Environment

Copy: ESP

NAF

HES



PUGET SOUND

AIR

POLLUTION

CONTROL

AGENCY

KING COUNTY

KITSAP COUNTY

PIERCE COUNTY

SNOHOMISH COUNTY

July 3, 1995

Gerald Brown Ash Grove Cement Co. 3801 E. Marginal Way S. Seattle, WA 98134 RECEIVED

JUL - 5 1995

AGCW-SEATTLE

Dear Mr. Brown;

Enclosed are Notices of Violations No. 33756 and 33757. NOV No. 33756 is being issued for the emissions observed June 29, 1995 as we discussed per phone. In addition to NOV No. 33290 for the June 22, 1995 incident, NOV No. 33757 adds Sections 9.15(a) and 9.15(c) for the emissions observed.

Please feel free to call me at 689-4056 if you have any questions.

Sincerely,

Melissa McAfee

Air Pollution Inspector

cc:

Elizabeth M. Gilpin, PSAPCA Rosemary G. Busterna, PSAPCA

Fred L. Austin, PSAPCA

MM\cbc

Dennis J. McLerran, Air Pollution Control Officer

BOARD OF DIRECTORS

Car 1

RECEIVED

PUGET SOUND AIR POLLUTION CONTROL AGENCY - 5 1995 110 Union Street, Suite 500, Seattle, Washington 98101-2038 Registration No._//339 AGCW-SEATTSF57 206-343-8800 / 1-800-552-3565 / Fax 206-343-7522 Cert. Mail No. NOTICE OF VIOLATION Date of Violation: Ash Grove Cement Company Gerald Brown, Sofety and Environmental Manager City Zip County Location of Violation (Address) 3801 E. Marginal Wy. S. Seattle, WA 98134 623-5596 3801 E. Marginal Wy. S. DID UNLAWFULLY CAUSE OR ALLOW VIOLATION OF: OF THE PUGET SOUND AIR POLLUTION CONTROL AGENCY FOR: Failure to develop and implement an operation and maintenance plan. Section 5.05(e) Failure to obtain Notice of Construction approval prior to construction/installation/establishment of a source. Section 6.03(a) Failure to meet conditions of an Order of Approval. Section 6.09(b) Visible emissions in excess of 20% opacity for periods aggregating more than 3 minutes/hour. Section 9.03(a) Particulate matter deposited in quantities/characteristics/duration so as to be injurious or interfere with enjoyment of life/property. Section 9.04 Emission of air contaminant in quantities/characteristics/duration so as to be injurious or interfere with enjoyment of life/property. Section 9.11(a) Emission of odor-bearing air contaminants without use of best available control technology. Section 9.12(b) Emission of fugitive dust without use of best available control technology. Section 9.15(a) Operation of vehicle on paved public roadway with dirt/mud/debris on undercarriage (track out) or load spillage. Section 9.15(b) Emission of fugitive dust from manufacturing process equipment or control apparatus. Section 9.15(c) Failure to apply VOC-containing material using spray equipment in an enclosed area with filtered exhaust and vertical stack. Section 9.16 Failure to operate and maintain equipment in good working order. Section 9.20 Section from the top of the clinker worker and of the kiln, (at shrond over couling).

CORRECTIVE ACTION ORDER

Under the provisions of Section 3.09 of Regulation I and RCW 70.94.211 you are ordered to submit a written report within ten (10) days of receipt of this Notice describing the necessary corrective action you have taken or propose to take, including a schedule, to achieve continuous compliance with the regulations, <u>and</u> take the following necessary corrective action:

Issued By MM (Gel Form No. 70-119 (Revised 9/93) 7/3/95/030 Date/Time Chy 7/3/95

Received By _

Signing this Notice is not an admission of guilt

AGCS2M000367

RECEIVED

4/3

PUGET SOUND AIR POLLUTION CONTROL AGENCY 5 1995

Registration No	11339
Cert. Mail No.	

Form No. 70-119 (Revised 9/93)

110 Union Street, Suite 500, Seattle, Washington 98101-2038 206-343-8800 / 1-800-552-3565 / Fax 206-343-7522

AGCW-SEABH-756

Signing this Notice is not an admission of guilt

AGCS2M000368

NOTICE OF VIOLATION

NOTICE OF			at 8:19 a
ate of Violation: 6 - 24	Responsible Person, Title		a
Name	•		
Ash Grove Cement Co.	Gerald Bro	ron, ich	oty Environmen
		Me	g na cier
Location of Violation (Address)	City	Zip	County
	Spattle	98/34	KING
3801 E. Marainal Illy. S. Mailing Address	City, State	Zip	Phone
. • • • • • • • • • • • • • • • • • • •			
3801 E. Marginal Wy S.	Seattle, WA	98134	623-559
DID UNLAWFULLY CAUSE OR	ALLOW VIOLAT	ION OF:	
	OUND AIR POLLUTION CO		Y FOR:
Section 5.05(e) Failure to develop and implement an operation and mainter Section 6.03(a) Failure to obtain Notice of Construction approval prior to consection 6.09(b) Failure to meet conditions of an Order of Approval. Visible emissions in excess of 20% opacity for periods agg Particulate matter deposited in quantities/characteristics/du Emission of air contaminant in quantities/characteristics/du Emission of odor-bearing air contaminants without use of best available consection 9.15(a) Emission of fugitive dust without use of best available consection 9.15(c) Emission of fugitive dust from manufacturing process equi Section 9.16 Failure to apply VOC-containing material using spray equi Failure to operate and maintain equipment in good working	onstruction/installation/establish regating more than 3 minutes/horation so as to be injurious or in iration so as to be injurious or in best available control technology trol technology. Id/debris on undercarriage (track pment or control apparatus. pment in an enclosed area with	our. terfere with enjoysterfere with enjoy	ment of life/property. ment of life/property. age.
☐ Section			
FACTS ALLEGED TO CONSTITUTE A VIOLATION Causing Han 20 hopicity for over 3 minutes in 1 clinker cooler and of the kilm. (at		nissions he top w cowli	of the
CORRECTIVE AC	TION ORDER		
Under the provisions of Section 3.09 of Regulation I and RCW 70.94.211 you are ordered the necessary corrective action you have taken or propose to take, including a schedule, to a necessary corrective action:	o submit a written report within achieve continuous compliance v	ten (10) days of re with the regulation	eceipt of this Notice describ is, <u>and</u> take the following
		~ AN	